SERVICE BULLETIN



www.apevibro.com

VIBRATORY HAMMERS • POWER UNITS AUGER SYSTEMS • DIESEL & HYDRAULIC HAMMERS Drill Rigs • Hydraulic Piling Rigs • Wick Drain Installers • Lead Systems

Dec. 28, 2015



www.jandm-usa.com

28 Repair/Replacement For Cracked Weld On Old Style Side Output Muffler

We are addressing the issue with the old style side output muffler cracking. Once the crack has started water will fill the engine and eventually cause a hydro lock in the cylinder.



We suggest checking these mufflers when they come into the yard. They can be cracked on the inside by the lifting nut, or on the outside where the large white circle is. If it is cracked it can be welded, if there is excessive damage replace it with a new style muffler.

See the below image for reference of an old style side muffler. If the mount is like the one circled in red it is the old model that will crack.





LOUISIANA REGIONAL OFFICE

39266 A DOYLE DRIVE

GONZALES, LA 70737

(225) 644-7722

FAX (225) 644-7626

APE HEADQUARTERS 7032 S 196TH STREET Kent, WA 98032 (800) 248-8498 • (253) 872-0141 Fax (253) 872-8710

NORTHEAST REGIONAL OFFICE 401 HARTLE ST. SAYREVILLE, NJ 08872 (888) 217-7524 • (732) 432-6604 FAX (732) 432-6608

SOUTHEAST REGIONAL OFFICE

1345 INDUSTRIAL PARK ROAD

Mulberry, FL 33860

(800) 570-3844 • (863) 324-0378

FAX (863) 318-9409

APE CHINA BUILDING No. 233, FU QIAO ROAD GU CUN INDUSTRIAL ZONE BAOSHAN DISTRICT Shanghai, China 201906 011-86-21-5677-1221 Fax 011-86-21-3604-0553

MID-WESTERN REGIONAL OFFICE 50 Gerber Industrial Dr. St. Peters, MO 63376

GULF REGIONAL OFFICE 3975 FM Hwy 1485 Conroe, TX 77306 (800) 596-2877 • (936) 271-1044 FAX (936) 271-1046

MID-ATLANTIC REGIONAL OFFICE 500 NEWTON ROAD, #200 Virginia Beach, VA 23462 (866) 399-7500 • (757) 518-9740 FAX (757) 518-9741

(877) 296-8044 • (636) 397-8400 FAX (636) 278-4278

WESTERN REGIONAL OFFICE 2985 LOOMIS ROAD STOCKTON, CA 95205 (888) 245-4401 • (209) 942-2166 Fax (209) 942-2455